

3 PHASE AUTO TRANSFORMER(WITHOUT COVER) SIZE REFERENCES

| TYPE | W | D | H | X | Y | Z | Weigh(kg) |
|--------|-----|-----|-----|-----|-----|-----|-----------|
| 10kVA | 420 | 180 | 360 | 360 | 130 | M10 | 56.0 |
| 17kVA | 420 | 220 | 360 | 360 | 170 | M10 | 81.4 |
| 20kVA | 420 | 280 | 360 | 360 | 230 | M10 | 121.6 |
| 27kVA | 420 | 270 | 360 | 360 | 220 | M10 | 114.2 |
| 35kVA | 420 | 220 | 420 | 360 | 170 | M10 | 98.2 |
| 40kVA | 495 | 270 | 475 | 425 | 220 | M10 | 201.2 |
| 45kVA | 555 | 310 | 487 | 485 | 235 | M10 | 182.3 |
| 70kVA | 570 | 360 | 542 | 500 | 285 | M12 | 224.6 |
| 80kVA | 570 | 330 | 542 | 500 | 255 | M12 | 253.5 |
| 90kVA | 570 | 330 | 542 | 500 | 255 | M12 | 260.6 |
| 100kVA | 570 | 290 | 712 | 500 | 215 | M12 | 295.0 |

